

# SOLIDWORKS – Quick Reference

Undo -----Ctrl + Z  
 Redo -----Ctrl + Y  
 Last Cmd -----Enter  
 Add/Remove Select -- Hold Ctrl  
 Tree Top -----Home  
 Tree End -----End  
 Collapse Tree -----Shift +C  
 Rename -----F2  
 Selection Filters -----F5  
 Filter Vertices -----V  
 Filter Edges -----E  
 Filter Faces -----X  
 Recent Documents -----R


**Force Rebuild**  
**Ctrl + Q**



**Rebuild All Configs**  
**Shift + Ctrl + Q**




## Customize Toolbars



## Heads Up Display




## User Interface Setup




## Dynamic Visualization

## Systems Options - Search




## Command Search "W" Key



Click Eye to Find  
 Drag Icon to  
 Toolbar to Add



## View Tool "Space Bar"




Zoom to Fit  
 "F" or Double  
 Mouse Wheel  
 Click



## Custom Properties



## Display Options – F8





## Hide/Show



With Cursor Over  
 Tab – Hide  
 Shift + Tab – Show


## Shortcut Toolbars "S" Key




## Mouse Gestures Right Click + Drag



## Recent Documents - R



## Switch Between Open Windows



Ctrl + Tab - Most Recent  
 +Tab – Cycle Options

## Move in Assembly



Left Click  
 + Drag

## Rotate in Assembly




Right Click  
 + Drag

## Right to Left



Fully  
 Enclosed  
 Selection

## Left to Right



Intersected  
 Selection